

WSR-88D SOFTWARE NOTE 9
(for Electronic Systems Analysts)

SUBJECT	:	Installation of Version 9.2 Software for the Principal User Processor (PUP) Group.
PURPOSE	:	To upgrade the PUP Software from previous version 9.0 to version 9.2.
SOFTWARE AFFECTED	:	PUP, CPCI-04.
PARTS REQUIRED	:	Installation instructions for PUP kit: 1 Software configuration matrix 1 SCSI tape containing PUP application files
SOFTWARE PROCUREMENT	:	The Operational Support Facility (OSF) will provide the kit for each site.
SOFTWARE TEST AND DEBUGGING TOOLS REQUIRED	:	None.
TIME REQUIRED	:	2.5 staff-hours for PUP installation.
EFFECT ON OTHER INSTRUCTIONS	:	None.
AUTHORIZATION STATEMENT	:	The authority for this software modification is OSF Emergency ECP F0048R3.
VERIFICATION STATEMENT	:	Version 9.2 software has been installed and successfully tested at the OSF, Norman, OK.

GENERAL

The purpose of this revision is to correct a latent graphic display processor problem using a software work-around. This revision affects only the PUP software. Version 9.0 of the PUP software should be retained for archival purposes. Map changes are not required.

Sites that do not have PUP version 9.0 loaded will need to load version 9.0 prior to loading version 9.2.

After a successful load of version 9.2 software, keep a backup copy of the previous version, the version 9.2 tapes, and the backup copy of version 9.2. Send all obsolete tapes to:

System Support Branch, Configuration Management
WSR-88D Operational Support Facility
3200 Marshall Ave Suite 101
Norman, Oklahoma 73072-8028

For additional information concerning this software note, contact the OSF Hotline, Norman, Oklahoma; phone number: (405) 366-2980 or 1-800-643-3363.

PROCEDURE

See attachments 1 and 2.

EFFECTIVITY

This software note applies to all WSR-88D PUP sites.

REPORTING NOTIFICATION

Target date for completion of this modification is 15 days after receipt of software note and kit. Report completed software change on WS Form A-26, Engineering Management Reporting System Maintenance Record, according to instructions in EHB-4, part 2, using equipment code PUP. Also, record the modification number in block 17a as S9 (see attachment 4 for a completed sample of WS Form A-26).

In addition, complete attachment 3 and fax or mail to:

System Support Branch, Configuration Management
WSR-88D Operational Support Facility
3200 Marshall Ave Suite 101
Norman, Oklahoma 73072-8028

Fax number: (405) 366-6553

Or e-mail information to:

chunt@osf.noaa.gov

Signed

John McNulty, Chief
Engineering Division

Attachments

Signed

James D. Belville, Director
Operational Support Facility